

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: May 19, 2014

Subject: Removal of 3J Knob Adhesive Sheet

This Product Advisory Notice is to alert you that Grayhill is making a design change to both the joystick and encoder version of the 3J Vehicle Display Controller (VDC).

Description of Change

Grayhill is removing the adhesive sheet between the top rubber insert and rigid plastic top cap.

Reason for Change

Originally, the adhesive sheet was used to mitigate the risk that the mechanical locking details would not retain the top cap when the unit was subjected to mechanical shock, vibration or high temperature and humidity. Subsequent testing showed this concern was unwarranted as parts without the adhesive sheet all passed the specified levels of shock, vibration and temperature cycling.

Effective Date

Grayhill will remove the adhesive sheet from future builds of 3J VDC assemblies starting July 1, 2014.

Part Numbers Affected

All part numbers constructed from the generic standard part numbers shown below are affected:

3J0005-200
3J0005-200N
3J0015-200
3J0015-200N
3J0115-200
3J0115-200N
3J1005-200
3J1005-200N
3J1015-200
3J1015-200N
3J1115-200
3J1115-200N
3J2005-200
3J2005-200N
3J2015-200
3J2015-200N
3J2115-200
3J2115-200N

Action Required

Please forward this notification to the appropriate person(s) in your organization. No other action is required. However, if you would like to receive a copy of the test reports or a free sample, please contact your Grayhill, Inc. sales associate.

