PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Rotary Switch Customers, Sales Representatives and Distributors

Date: July 25, 2014

Subject: 2D Barcode Added to Rotary Switches

This Product Advisory Notice is to alert you that there is a coming change to Grayhill rotary switches and our records show that your company has purchased one or more of the affected part numbers in the past. Please forward this notification to the appropriate person(s) in your organization.

Description of the Change

A 2D barcode will be added to the label that is applied to each rotary switch. This barcode will contain a 4 digit date code and a 5 digit serial number. A representative sample of the new label is shown below. No changes will be made to the human readable information that appears on the label.



Reason for Change

The new label will improve traceability of switches through the manufacturing process and after they have been sold.

Effective Date

The new labels will begin to be implemented starting Sept. 1, 2014

Part Numbers Affected

All Grayhill rotary switches that have part numbers beginning with:

08	51
09	53
19	54
20	56
24	57
25	58
26	59
42	71
43	75
44	5000
50	

Action Required

Please forward this notification to the appropriate person(s) in your organization. No other action is required. If you have any questions, contact your Grayhill, Inc. sales associate.

 Schwww.grayhill.com
 Bulletin #1230
 Page 1
 07/25/2014