

# PRODUCT ADVISORY NOTICE

---

## KEEPING YOU INFORMED OF PRODUCT CHANGES

---

**To:** All Customers, Sales Representatives and Distributors

**Date:** September 19, 2016

**Subject:** 60A Joystick - Internal Change to the PC Board

This Product Advisory Notice is to alert you that there is a coming change to all standard Grayhill Series 60A joystick encoders that your company purchases. ***Please forward this notification to the appropriate person(s) in your organization.***

### **Description of Change**

Grayhill has made a minor change to the internal pad layout of the PC board. The change was made as a product improvement to make the internal tact switch connection more robust. Currently, the tact switch is attached to the board via four pads. Grayhill has added an additional fifth pad to the PC board. This will provide one extra attachment point between the tact switch and the PC board. This change does not affect the customer in any way since all changes are internal to the joystick. This change does not affect the form, fit, or function of the joystick.

### **Reason for Change**

Product improvement.

### **Effective Date**

This change will be phased in on date code 1642 (October 17).

### **Part Numbers Affected**

All 60A products.

### **Action Required**

No action required. Should you need further assistance or a sample of this change, please contact your Grayhill, Inc. sales associate.

