

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

TO: All 08LL36 and 50LL36 Keylock Switch Customers,
Sales Representatives, and Distributors

DATE: 01/30/24

SUBJECT: Obsolescence of 36 degree 08LL and 50LL Keylock Switches

Description of Change

Grayhill is discontinuing the sale of 08LL36 and 50LL36 keylock switches.

Reason for change

The 36° keylock components are no longer available from Grayhill's supplier.

Part Numbers Affected

08LL36-01B10N	08LL36-02-2-05S	08LL36-03-2-03N	08LL36-04-1-07N	08LL36-04-2-03N
50LL36-01-1-04N	50LL36-01-1-08N	50LL36-01-2-02S	50LL36-01-2-04N	50LL36-01-2-05S

Effective Date

01/30/24

Action Required

Please forward this notification to the appropriate person(s) in your organization.



GRAYHILL

561 West Hillgrove Avenue • La Grange, Illinois 60525 USA • (+1) 708-354-1040
www.grayhill.com Bulletin #1366 Page1 1/30/2024