

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives, and Distributors

Date: August 1, 2013

Subject: This Product Advisory Notice is to alert you that Grayhill is modifying our product.

Please forward this notification to the appropriate person(s) in your organization.

Description of Change

Grayhill is making a minor design change to the joystick shaft, by reducing the pivot ball diameter by 0.002 inch (0.05mm). This change will have no impact on form, function, or feel of the joystick.

Reason for Change

Beyond the cold extreme of the operating temperature range (-40°C for 4 hours) when the joystick shaft is pressed to activate the pushbutton function, the button may remain depressed. As the joystick warms up it functions normally.

Effective Date

This is a running change that will be implemented in product produced after August 26.

Part Numbers Affected

3J0115-100
3J0115-100N
3J0115-200
3J0115-200N
3J1105-100
3J1115-100
3J1115-100N
3J1115-200
3J1115-200N
3J2115-100
3J2115-100N
3J2115-200
3J2115-200N

Action Required

Please advise the appropriate Engineering, Manufacturing and Procurement personnel within your organization of this change. If further information is required, please contact your local sales representative or call Grayhill directly at (708) 354-1040.

