# PRODUCT ADVISORY NOTICE

**KEEPING YOU INFORMED OF PRODUCT CHANGES** 

## TO: All 75 Series Rotary Switch Customers, Sales Representatives and Distributors

DATE: 06/18/2024

## SUBJECT: Contact material change for non-shorting switches to maintain RoHS compliance

This Product Advisory Notice is to alert you that there is a coming material change to all non-shorting versions of 75 series rotary switches. Our records show your company has purchased one or more of the affected part numbers in the past. Please forward this notification to the appropriate person(s) in your organization.

## **Description of Change**

Grayhill is changing the non-shorting contact material from silver cadmium-oxide to silver tin-oxide.

#### Reason for change

The RoHS exemption for cadmium and its compounds in electrical contacts is set to expire in July 2024.

## Effective Date

The material change will be implemented before July 21, 2024.

## Part Numbers Affected

For a complete list of part numbers, please see the attached sheets. An electronic copy of this list in MS Excel or CSV format can be requested from your Grayhill, Inc. sales associate.

## Test Data Available

Samples have been made using the new material and have passed our qualification testing. Full test reports are available upon request.

## Action Required

Please forward this notification to the appropriate person(s) in your organization. If the change is acceptable, no action is necessary. If you have questions, contact your Grayhill, Inc. sales associate.

1375 Component Listing				
75AF36-01-1-03N	75BF36-01-1-03N	75CF36-01-1-05N	75YY50024	75YY50572
75AF36-01-1-05N	75BF36-01-1-04N	75CF36-01-1-08N	75YY50027	75YY50573
75AF36-01-1-06N	75BF36-01-1-05N	75CF36-01-2-04N	75YY50032	75YY50574
75AF36-01-1-08N	75BF36-01-1-06N	75CF36-01-2-05N	75YY50033	75YY50575
75AF36-01-2-02N	75BF36-01-1-07N	75CF36-01A10N	75YY50036	75YY50576
75AF36-01-2-03N	75BF36-01-2-04N	75CF36-01B10N	75YY50039	75YY50578
75AF36-01A10N	75BF36-01A10N	75CP36-01-1-04N	75YY50043	75YY50579
75AF36-01B10N	75BF36-01B10N	75CP36-01-1-06N	75YY50044	75YY50582
75AP36-01-1-02N	75BP36-01-1-02N	75CP36-01-1-08N	75YY50047	75YY50583
75AP36-01-1-03N	75BP36-01-1-03N	75CP36-01-1-09N	75YY50052	75YY50584
75AP36-01-1-04N	75BP36-01-1-04N	75CP36-01-2-04N	75YY50561	75YY50588
75AP36-01-1-05N	75BP36-01-1-06N	75CP36-01-2-05N	75YY50562	75YY50590
75AP36-01-1-06N	75BP36-01-1-07N	75CP36-01A10N	75YY50563	75YY50593
75AP36-01-1-07N	75BP36-01-1-08N	75CP36-01B10N	75YY50564	75YY50595
75AP36-01-1-08N	75BP36-01-2-03N	75BY23025	75YY50565	75YY50601
75AP36-01-2-02N	75BP36-01-2-04N	75BY23046-2-03N	75YY50566	75YY50602
75AP36-01-2-04N	75BP36-01-2-05N	75BY23106	75YY50567	75YY50606
75AP36-01-2-05N	75BP36-01A10N	75YY50017	75YY50568	75YY50607
75AP36-01A10N	75BP36-01B10N	75YY50019	75YY50569	75YY50608
75AP36-01B10N	75CF36-01-1-03N	75YY50021	75YY50570	75YY50610



561 West Hillgrove Avenue • La Grange, Illinois 60525 USA • (+1) 708-354-1040 www.grayhill.com Bulletin #1375 Page1